



Oxygen or air can be chosen as gas supply of small animal anesthesia machines. Air pump (R510-29/R510-30) can provide air as gas supply; medical oxygen and E-oxygen tanks can provide oxygen as gas supply (you need to buy oxygen relief valve (R-GM-ET(S)) for Oxygen tanks, E-oxygen tanks are only suitable for portable anesthesia machines and need to purchase E-oxygen tank (R-GM-ET(S)) or double tanks (R-GM-ET(D)) mounting bracket, (as shown above), oxygen is provided by the user.