


Portable Small Animal Warming Plate

Prevent hypothermia during surgery, post-surgery & anesthesia induction



Warming Plate Temp Range
~31°C • ~35°C • ~45°C

USE: Use under animal during surgery & post surgery to prevent hypothermia. Place in induction chamber during anesthesia to prevent hypothermia.

- Small enough to place under animals during stereotaxic surgery.
- Can be place on bench or in cage.
- Non-skid feet for added stability.
- HD power supply with universal input for use in any country (100 – 240 VAC, 50-60 Hz).
- Size: 17 X 10 cm, Stainless Steel.



Ref: **VI-PWPV** Portable Warming Plate w/ Variable Power Supply